

Non-Contact Automatic Infrared Thermometer



S-AIRT



**Quick
Measurement**



**High
Accuracy**



**1 Week
Standby**



Alarm



**Unit
Available**



**Energy
Saving**

Features:

- Non-contact Forehead Thermometer
- Safe & Hygienic
- Large LCD Digital Display Screen
- Fast And Easy Temperatures Readings
- Great Accurate Readings
- Fever Alarm

Specification:

Accuracy	: ± 0.2 degrees
Infrared Measuring Range	: 0°C ~ 50°C
Abnormal Automatic Alarm	: Flashing + "Di Di" Sound
Automatic Measurement	: Measuring distance 5cm~10cm
Standby	: About 1 Week
Response Time	: 0.5s
Charging Method	: USB Charging or battery
Input	: USB DC 4.2 ~ 5V
Screen	: Digital Display
Standby	: 5s (Red dot dynamic cycle)
Weight	: 350g
Dimensions	: 170x115x140mm
Install Method	: Nail Hook, Double-sided adhesive sticking, Bracket fixing
Operating Temperature	: 10°C ~ 40°C (Recommend 15°C ~ 35°C)